Reply to Office Action of August 17, 2004

## Amendments to the Specification:

Please replace the paragraph beginning at page 6, line paragraph [0035], with the following rewritten paragraph:

[0035]

Each of the left and right vertical plates 32 has vertically extending holes 32b formed on its band-shaped support member 32a 32b-vertically extending. The windshield 30 is secured to the vertical plates 32, 32 with bolts 32c inserted through the vertically extending holes 32b so that the vertical position of the windscreen 30 can be adjusted.